

Round/Mother

M-Mills (3 Mills)

Shapes

0.610	Partial set shape only / uses Break downs from .625 round	.500 SQ		
0.625	Complete set round only			
0.750	Complete set round only / uses T-Head sonly for .625 SQ	.625 SQ		
0.840	Complete set round only			
0.875	Complete set round only			
0.905	Complete set shape only .750 SQ / Partial .5 x 1	.750 SQ	.500 x 1.000	
1.000	Complete set round / Partial .813 SQ stand 2 and 3 only			
1.125	Complete set shape only		.500 x 1.250	
1.220	Complete set shape only			.750 x 1.375
1.250	Complete set / Partial .5 x 1.5 and .875 x 1.5		.500 x 1.500	.875 x 1.500
1.250	Complete set / Partial 1 x 1	1.000 SQ		
1.625	Complete set round only			
1.875	Complete set round / Partial 1.5 SQ and 1 x 2	1.500 SQ	1.000 x 2.000	
2.031	Complete set shape only		2.000 x 1.250	
2.125	Partial set round only uses 2.375 breakdowns			
2.250	Partial set round only uses 2.375 breakdowns			